

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

2324 WEST LAUREL STREET (HOUSE)

HABS FL-510

West Tampa

Tampa

Hillsborough County

Florida

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Penny Rogo Bailes, photographer, December 2004

- | | |
|----------|---|
| FL-510-1 | CONTEXT VIEW OF NORTH FRONT AND EAST SIDE OF
2324 WEST LAUREL STREET, FACING SOUTHWEST |
| FL-510-2 | CONTEXT VIEW OF NORTH FRONT AND WEST SIDE OF
2324 WEST LAUREL STREET, FACING SOUTHEAST |
| FL-510-3 | VIEW OF NORTH FRONT OF 2324 WEST LAUREL STREET,
FACING SOUTH |
| FL-510-4 | VIEW OF EAST SIDE OF 2324 WEST LAUREL STREET,
FACING SOUTHWEST |
| FL-510-6 | VIEW OF SOUTH REAR AND EAST SIDE OF 2324 WEST
LAUREL STREET, FACING NORTHWEST |
| FL-510-7 | VIEW OF SOUTH REAR OF 2324 WEST LAUREL STREET,
FACING NORTH |

Penny Rogo Bailes, photographer, April 2005

- | | |
|----------|---|
| FL-510-5 | VIEW OF WEST SIDE OF 2324 WEST LAUREL STREET,
FACING EAST |
| FL-510-8 | INTERIOR VIEW OF FIRST FLOOR LIVING ROOM AND
DINING ROOM AT 2324 WEST LAUREL STREET, FACING
SOUTH |

2324 WEST LAUREL STREET (HOUSE)

HABS FL-510

INDEX TO PHOTOGRAPHS

FL-510-9	INTERIOR DETAIL VIEW OF FIRST FLOOR FIREPLACE AT 2324 WEST LAUREL STREET, FACING EAST
FL-510-10	INTERIOR DETAIL VIEW OF DOOR IN FIRST FLOOR REAR BEDROOM AT 2324 WEST LAUREL STREET, FACING NORTH
FL-510-11	INTERIOR DETAIL VIEW OF ARCHED DOOR OPENING FROM SECOND FLOOR LIVING ROOM TO HALL AND BATHROOM AT 2324 WEST LAUREL STREET, FACING SOUTH
FL-510-12	INTERIOR DETAIL VIEW OF WINDOWS IN SECOND FLOOR NORTH BEDROOM AT 2324 WEST LAUREL STREET, FACING NORTHWEST
FL-510-13	INTERIOR DETAIL VIEW OF DOOR IN SECOND FLOOR NORTH BEDROOM AT 2324 WEST LAUREL STREET, FACING SOUTHEAST
FL-510-14	INTERIOR DETAIL VIEW OF WINDOWS IN SECOND FLOOR UTILITY ROOM AT 2324 WEST LAUREL STREET, FACING SOUTH